

<u>TERMITE INSPECTION REPORT</u>		1. REALTOR/ESCROW CO. Escrow Service, Inc. 10310 Chester Drive Honolulu, HI 96813	2. DATE REPORT PREPARED 10/15/2007
EXISTING CONSTRUCTION			3. ESCROW # 10307
4. NAME/ADDRESS OF LICENSEE (Include ZIP Code) BidDay AssetXray Report PO Box 2831 Honolulu HI 96813 P.C.O. # 123456		5. NAME OF INSPECTOR Sam Eagleye	
6. NAME, ADDRESS AND TELEPHONE NUMBER OF PERSON ORDERING INSPECTION BidDay AssetXray Report PO Box 2831 Honolulu, HI 96813 800 689-0233		7. ADDRESS OR LOCATION OF BUILDING OR PROPERTY INSPECTED 10300 Chester Drive Honolulu, HI 96813	
8. INSPECTION DATE: Wed, Oct 17, 2007		9. (a) DATE OF LAST TREATMENT FOR BUILDING OR PROPERTY INSPECTED: 10/9/2007	
10. SELLER'S/OWNER'S NAME: John		(b) SOURCE OF INFORMATION FOR LAST TREATMENT: New Image Software, Inc.	
11. BUYER'S NAME: Jack		(c) WAS SELLER'S DISCLOSURE STATEMENT RECEIVED? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
SCOPE OF INSPECTION			
<p>12. This report documents the results and scope of an inspection of the above address for the presence of termites. This report does not include identification or detection of microorganisms. This report is made on the basis of a visual inspection of areas which were accessible to the inspector at the time of the inspection. As to such areas which were obstructed, enclosed, or concealed from the view of the inspector, or any area of the structure for which inspection may result in damage, removal or defacement of part of the existing structure, this report does not, and should not be construed to, present any finding and/or opinion as to the presence or absence of termites. Areas which were obstructed, enclosed or concealed may include the following: fixed ceilings, spaces between double walls, stored articles of personal property, hidden joists or rafters, under and behind floor and wall coverings, floor and wall cabinets, furniture, and appliances, including crawl spaces of less than 24" from the bottom of the floor joist to the surface below. The PCO should list the Report of Findings, those obstructed, enclosed or concealed areas in which no inspection could be conducted.</p> <p>13. This inspection report is not, and should not be construed as</p> <p>(a) Constituting a guarantee or warranty (implied or expressed) as to the absence of termites in the inspected structure (see Section 460J-19(b), Hawaii Revised Statutes); or</p> <p>(b) Presenting any opinion as to the structural integrity of the building due to termite infestation, or the necessity or cost of repair. If visible damage to the structure(s) is noted below, further investigation by qualified professional construction or engineering persons may be warranted; or</p> <p>(c) Constituting a finding and/or opinion as to the potential for subsequent termite infestation as to accessible or inaccessible areas.</p> <p>14. The information contained in this report is considered to be reliable for not more than fifteen (15) days subsequent to the date of inspection. This report shall not be assigned, sold or otherwise transferred to third persons without the express written consent of the Licensee noted above.</p> <p>15. The Licensee above named shall not be liable or responsible for damages due to subsequent termite infestation in and to areas of the building or property inspected UNLESS the presence of termites in such areas was visible to the inspector at the time of the inspection (Section 460J-19(b), Hawaii Revised Statutes).</p> <p>16. Other than for inspection purposes, neither the Licensee nor the inspector has now, or contemplates having, any financial, ownership, or possessory interest in the property inspected. Neither Licensee nor inspector is associated with any party to a transaction involving the transfer of an interest in the property.</p> <p>17. If available, the seller's disclosure statement should be supplied prior to this report.</p>			
REPORT OF FINDINGS			
18. General description of the building or premises inspected (i.e. residential or commercial; number of buildings, appurtenant structures etc.)			

19. Were any areas of the building or premises obstructed, enclosed, or otherwise concealed from inspection?

Yes No

Describe those areas and state the reasons any accessible area was not inspected.

20. Was visible evidence of termite infestation observed?

Yes No

Due to the cryptic nature of termites it may not be possible to determine conclusively whether or not termites are present simply based on visible evidence of termite infestation. Destructive testing or damage to the premises may be necessary to detect infestations.

(a) Drywood Subterranean

(b) Describe location(s). Also note on a diagram of the building or premises attached to the report.

21. Is further action for control of drywood and/or subterranean termites recommended?

Yes No

(a) Recommendations:

(b) State whether any existing conditions of the premises contain the potential for future termite infestation. Examples of some conditions conducive to termite infestation are: earth-to-wood contact, leaking roof, or roof damage, wood debris in crawl space and excessive moisture or water exposure. The PCO does not and cannot advise as to the presence or absence of any other damage to the structure or premises, or in inaccessible areas including, but not limited to retaining walls, hidden (concealed) construction joints, stucco siding below grade, bath traps, plumbing blockouts and penetrations or damage caused by fire, water, rot, moisture, microorganisms, humidity, flood, leaks or storms.

22. Additional Comments:

23. Copies of this report have been provided to:

Realtor/Escrow Owner/Seller Purchaser

24. _____


Signature of Authorized Licensee

Thu, Oct 18, 2007

Date

DIAGRAM OF STRUCTURE INSPECTED

Add diagram of structure inspected below. Diagrams typically are not drawn to scale. The diagram should have a description of the building: i.e., 3 bedroom structure, floors, etc. Describe by location on diagram and in writing appropriate areas of infestation.



Additional Comments:

Wood Destroying Insect Inspection Addendum

Inspector's Name:

Sam Eagleye

Property Address:

10300 Chester Drive

Honolulu, HI 96813

Date

Wed, Oct 17, 2007

FHA/VA Case No.

10307

Notes go here

INSPECTION PHOTOS



#



1



2



3



4



5